
1.8Cordless Brushless Impact Driver

ADPL04-8/DCPL04-8/KDPL04-8



DCPL04-8

No	Code	Name of Spare Parts	Remark
1	30021600033	Retaining Ring For Shaft 12	
2	30021600173	Washer 7 (12×15×0.5)	
3	30024500066	Compression Spring (13.2×0.7×15)	
4	30029902734	Chuck Cover	
5	30021000010	Steel Ball 3.5	
6	30010000602	Rubber Sleeve	
8	30010300264	O Ring	
10	30016300038	Nylon Washer	
11	30020100261	Drive Spindle	
12	30029902704	Impact Block	
13	30020500513	Planet Gear	
14	30029900178	Pin	
15	30021600103	Washer (18×12.5×1)	
16	30020500134	Annular Gear	
17	30010300019	O Ring (38×2)	
18	30021400197	Ball Bearing 61801 2RS	
19	30019901954	Rear Cover Of Gearbox	
21	30021400234	Ball Bearing 295	
23	30400300019	Stator	
24	30015500046	Rear Cover (Blue)	
25	30021200062	Pan Head Tapping Screw ST2.9×16	
26	30019901940	Reversing Switch Lever (Red)	
27	30030100404	Switch	
28	30019900109	Terminal Block	
33	30029902703	Hook	
34	30021100680	Cross Recessed Pan Head Screw M2.5×7.5	
37	30024000220	Clamping Plate	
38		Battery Pack	
39		Battery Charger	
T1	30009801193	Front Housing Of Gearbox Assembly	Including：7、9
T2	30200200029	Armature Assembly	Including：20-22
T3	30009801195	Controller	Including：29,30
T4	30415400255	Motor Housing Assembly (DongCheng)	Including：35,36
T5	30240900215	Plastic Case(DCA)& PS Lining	

