


Activa
Go to S

QG-610D explosive view

PARTS LIST AND SCHEMATIC DRAWING

No	DESCRIPTION
1	Plastic tube
2	Steel tube
3	Micanite paper tube
4	Heating element
5	Fan cave
6	screw
7	Fan blade
8	screw
9	Motor base
10	D.C. motor
11	Switch

No	DESCRIPTION
12	Switch plate
13	screw
14	Cord grip
15	Power cord
16	Button PCB
17	Button
18	Tail hood
19	screw
20	housing