

16
X6
5
7
9
10
15
x2
8
x3
6
11
12
x2
13
17
4
3
14
2
1

QG-001 explosive view

PARTS LIST AND SCHEMATIC DRAWING

No	DESCRIPTION
1	Plastic tube
2	Steel tube
3	Micanite paper tube
4	Heating element
5	Fan cave
6	screw
7	Fan blade
8	screw
9	Motor base
10	D.C. motor
11	Switch

No	DESCRIPTION
12	screw
13	Cord grip
14	Power cord
15	Knob
16	screw
17	housing

