
Exploded view : CS400 เครื่องลับใบเลื่อยวงเดือน





Exploded view : CS400 เครื่องลับใบเลื่อยวงเดือน

PARTS LIST

1	Motor Cover	42	Screw
2	Switch	43	Screw
3	Power Cord Support	44	Screw
4	Screw	45	Finger
5	Switch Circuit Board	46	Angle Guide Right
6	Screw	47	Guide Right
7	Washer	48	Screw
8	Motor	49	Screw
9	Motor Housing	50	Steel Bushing
10	Motor Neck	51	Screw
12	Connecting Piece	52	Front Guiding Bushing
13	Bearing Bushing	53	Adjust Base
14	Retaining Ring	54	Screw
15	Pin	55	Screw
16	Bearing	56	Pull Rod
17	Retaining Ring	57	Screw
18	Bearing	58	Left Guiding Bushing
19	Arbor	59	Washer
20	Screw	60	Side Handle
21	Protection Cover	61	Screw
22	Grinder Lock Cap	62	Handle
23	Grinding Disk	63	Swivel Arm
24	Grinding Wheel Base	64	Mandrel Swivel Arm
25	Screw	65	Washer
26	Disk Cover	66	Saw Blade Support
27	Screw	67	Screw
28	Screw	68	Washer
29	Protection Plate	69	Rubber Feet
30	Screw	70	Washer
31	Power Cord Protector	71	Screw
32	Power Cord	72	Retaining Ring
33	Angle Guide Left	73	Swivel Arm Saw Blade Catch
34	Steel Bushing	74	Base
35	Nut	75	Screw
36	Motor Retainer Complete	76	Mandrel Swivel Arm
37	Screw	77	Washer
38	Rear Guiding Rod	78	Ring
39	Screw	79	Blade Stop
40	Screw	80	Screw
41	Right Guiding Bushing	81	Pressure Bushing
		82	Spring
		83	Lock Nut