Andon light wireless solutions for machine monitoring & workstation call-for-action systems



WERMA

Easy steps to manual work station monitoring...

1

Select your signal tower modules




184-5126


184-5128


184-5127


455-3407


314-7332

+

2

Add a transmitter to your system


184-5124

+

3

Add a manual controller


849-5403

4

Install ethernet master & software on your network


184-5123

5

Monitor from your PC