Date: 25/01/2024

910.13 SS G1/2B / G1/2 LH-RH union 2…6 bar

Overpressure protector, adjustable

Item number:	9091521
Quantity:	1 pcs.
Order code:	910.13-SS1B2-1ZZ-F71-ZZ 0
Overview:	910.13 SS G1/2B / G1/2 LH-RH union 2…6 bar Overpressure protector, adjustable Material body: Stainless steel 1.4571 Connection process side + instrument side: G 1/2 B male + G 1/2 LH-RH union Material sealing : FPM Permissible medium temperature: -10...+80°C Setting range: 2…6 bar Factory setting, set at: 4 bar
Details:	Overpressure protector, adjustable Specifications according to data sheet: AC 09.04 Special design features: NACE Sour Gas Service Material body: Stainless steel 1.4571 Material sealing : FPM Permissible medium temperature: -10...+80°C Connection process side + instrument side: G 1/2 B male + G 1/2 LH-RH union Overpressure safety: 1000 bar Setting range: 2…6 bar Factory setting, set at: 4 bar

© 2024 - WIKA Instruments s.a.r.l.