
# E40100

## Screw-in adapter for process sensors

Adapter SI0/M12x1/MS




| | | |
|---|---|---|
| **Application** | | |
| Application | | for industrial applications |
| Media | | liquids and gases |
| Pressure rating | [bar] | 30 |
| **Tests / approvals** | | |
| Pressure Equipment Directive | | A possible classification to PED depends on the application and has to be carried out by the user / operator. |
| Pressure Equipment Directive EAC | | The adapter is intended for use in devices, machines and installations that do not fall under the categories of the technical rule TR CU 032/2013. |
| Safety instructions | | The compatibility between medium and product material has to be checked in all applications. |
| **Mechanical data** | | |
| Weight | [g] | 59.1 |
| Dimensions | [mm] | M18 x 1.5 |
| Thread designation | | M18 x 1.5 |
| Materials | | brass (2.0401) |
| Sensor connection | | M18 x 1,5 internal thread |
| Process connection | | threaded connection M12 x 1 |
| Insertion depth | [mm] | 13.5; (measuring probe SID, SFD, TN) |
| **Accessories** | | |
| Items supplied | | sealings: 1, AFM |
| **Remarks** | | |
| Remarks | | In applications >30 bar use a suitable high-pressure adapter. |
| Pack quantity | | 1 pcs. |