Royston

7220N2TF1



SIOSTART MODULAR

Flame retardant fleece lining

This flame retardant sleeveless fleece lining protects you not only against flames and its spreading, but also against the cold. This lining cannot be worn separately. It has undergone anti-pilling treatment and has a handy slit pocket connected to the inside pocket of the raincoat in which it can be zipped.

EN ISO 14116: 2015	EN 14058 2017
Index 1	1 1 x x

Flame retardant fleece lining

Royston - 7220N2TF1

European Standards: *(based upon size L)*

- EN ISO 14116 : 2015 / IND. 1
- EN 14058 : 2017 / Class 1 1 xx
- EN ISO 13688 : 2013

Exterior:

- Back length 65 cm (L)

Fabric:

Double sided fleece: 100% flame retardant polyester; ± 275 g/m²

Sizes:

S - XXXL

Colour:

- B75 Navy blue

I.L.S.:

7218 – 7219 – 9396

Packaging:

5 pieces per box

Wash and care instructions:



SIOEN head office
Fabriekstraat 23
B-8850 Ardooie
Belgium
T: +32 (51) 740 800
F: +32 (51) 740 962
www.sioen-ppc.com

© 2022 Sioen Apparel - Protection through Innovation. *Flexothane®*, *Siopor®* and the *SIOEN* logo are trademarks of the Sioen Industries Group.

Please note that all information given in this document is intended to be useful and informative and is correct to the best of our knowledge at time of print. No liability can be accepted for inaccuracies or omissions. The right is reserved to amend this information without prior notice. All our technical files, style descriptions, presentations, designs and drawings, give the latest update of the standards and design or style features of each product. However, delivered products may comply with previous standards, design or style features. For that Sioen disclaims any liability whatsoever. Contact our sales for full information if specific requirements are needed.

Discover our products

Modification date: 06-03-202409:56

Copyright © 2022 Sioen Industries. All rights reserved. info@sioen.com
Sioen nv is a subsidiary of the Sioen Industries Group. Real textile colours may slightly differ from the printed ones. We are not responsible for printing errors.