Control Stations ø 22

CONTROL STATIONS - NON-ILLUMINATED

Technical Info (p. 103)

SPRING RETURN - FLUSH



LBX20120



			Marking	
● Green	NO	3 4	I	
● Red	NC	1 2	O	**LBX20120**

SPRING RETURN - FLUSH/MUSHROOM



LBX210660



			Marking	
● Green	NO			
● Red	NC	3 4 / 1 2	I / O	**LBX210660**

SPRING RETURN/MAINTAINED - FLUSH/MUSHROOM (PUSH-TURN)



LBX210770



			Marking	
● Green	NO	3 4	I	
● Red	NC	1 2	O	**LBX210770**