FOKC

Fiber Optic Kevlar® Cutter

***Warning*! <u>This tool should not be used on live electrical circuits.</u> <u>It is not protected against electrical shock!</u>** Always use **OSHA/ANSI** or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool.

NOTE: This tool has been specifically designed for the cutting of aramid yarn (also referred to as KEVLAR®) found in fiber optic cables. **It is not intended for cutting the solid central strength member in fiber optic cables, coaxial cables, twisted pair or other communication or electrical cables.**

Use an industry approved cable gel cleaner or degreaser to clean residue on the cutting edges after use on cables containing water blocking gel.

WARRANTY: The Ripley Company warrants that our line of tools are free of defect and fully operable at the time of shipment. The warranty is limited to the repair or replacement of any product which proves to be defective in material or workmanship, under normal use and service.

RIPLEY®
46 Nooks Hill Road
Cromwell, CT 06416
Phone: 800-528-8665
Int'l: (01) 860-635-2200
Fax: (01) 860-635-3631
E-mail: info@ripley-tools.com
Internet: www.ripley-tools.com

MILLER®
36497
9/7/00
Rev 1