

DSS125B

No	Code	Name of Spare Parts	Remark
1	30021100086	Cheese Head Screw M6×16	
2	30024300023	Wheel Guard	
4	30019900181	Sleeve	
5	30021600140	Backing Pad62×14×1.5	
7	30029900048	Bush	
8	30024000182	Gear Housing Coverplate	
9	30025300010	Bush	
10	30050900020	Felt Ring	
11	30021400067	Ball Bearing 6003DD (LFB)	
12	30021700001	Woodruff Key 3×3.7×10	
13	30020100032	Drive Spindle	
14	30021700002	Woodruff Key 4×5×13	
15	30021300046	Hex Nut M14	
17	30021100070	Countersunk Head Screw M4×14	
18	30021100089	Small Pan Head Screw W/Washer M5×16	
19	30024000183	Strap Holder	
20	30024000184	Strap Buckle	
21	30023300039	Gear Housing	
22	30010300077	O Ring	
24	30025300009	Spacer Ring 17×23×7	
25	30020500069	Gear	
26	30021600014	Circlip for Shaft17	
27	30023400041	Motor Bracket	
28	30010300044	O Ring (32×2)	
29	30021400300	Ball Bearing 6201DDU-DC06	
30	30016000011	Baffle Plate	
31	30400401657	อะไหล่ฟันไฟฟ้า DSS125B	220V
32	30024000185	Band 2	
33	30021200018	Pan Head Tapping Screw	
34	30415400079	Motor Housing (DongCheng)	
36	30016300010	Insulation Washer	
37	30021400354	Ball Bearing 608-2RS-DC015	
38	30010400004	Damping Washer (22×25×3)	
39	30022000001	Bearing Retainer	
40	30021200026	Pan Head Tapping Screw ST5×63	
41	30400600098	อะไหล่ฟิลคอยล์ DSS125B	220V
42	30030700002	Brush Holder Assembly	
43	30021100096	Hexagon Socket Screws W/Flat Point M5×8	
44	30030600018	Carbon Brush	
45	30030800002	Brush Holder Cap	
46	30030400007	Capacitor 0.33μF	
48	30021200001	Pan Washer Head Tapping Screw ST4×12	
49	30016400009	Terminal Block Cover	
50	30030100059	Switch	110-220V
51	30030400017	Terminal Block	
52	30021200008	Pan Washer Head Tapping Screw ST4×16	
53	30016300006	Strain Relief	
55	30021200048	Pan Head Tapping Screw ST4.2×17	
56	30010100033	Cord Guard (PVC)	
57	30030300078	Power Cord (European Standard Plug)	220V
58	30021200002	Pan Washer Head Tapping Screw ST5×20	
60	30050900045	Paper Pad	
61	30021600054	Standard Spring Washer 14	
861	30025100007	Wrench	
862	30019900267	Big Sleeve	
T1	30005090082	ชุดปะกับในนอก+ใน	Including: 6,16
T2	30005090118	เสียด้านสวิตช์	Including: 54,59

