


STUBBY SCREWDRIVER

Models	Driver type(mm)	Axis Across Flat (mm)	Dimensions (mm)			Qty./ Carton	Weight (g)
			D	A	L		
SD-M	$\ominus 0.8 \times 7.2$	6	31	23	70	12	40
SD-P	$\oplus$ No.2	6	31	23	70	12	40

- With magnet
- Square shaft screwdriver / Hexagon shaft screwdriver



WARNING

- Plastic handle is not for insulation. Do not use on live lines.

CAUTION

- It is not a bit-through type screwdriver.

Short length makes this tool most suitable for working in a confined space.



MINI STUBBY SCREWDRIVER SET

Models **SSD2**

Contents **2 Items**

Models	SSD-	M2	P2
Driver type	$\ominus 0.8 \times 7.2$	$\oplus$ No.2	
Length(mm)	14	14	


- With magnet
- Square shaft screwdriver / Hexagon shaft screwdriver
- Weight : 0.35kg
- Qty./Carton : 1



MINI STUBBY SCREWDRIVER

Models	Driver type (mm)	Axis Across Flat (mm)	Dimensions (mm)			Qty./ Carton	Weight (g)
			D	A	L		
SSD-M2	$\ominus 0.8 \times 7.2$	6	30	14	30	1	15
SSD-P1	$\oplus$ No.1	6	30	14	30	1	20
SSD-P2	$\oplus$ No.2	6	30	14	30	1	20

- With magnet
- Square shaft screwdriver / Hexagon shaft screwdriver



WARNING

- Plastic handle is not for insulation. Do not use on live lines.

CAUTION

- It is not a bit-through type screwdriver.

A design that is even shorter than a stubby driver.



SSD2




SSD-P2

SSD-M2

BABY SCREWDRIVER

Models	Driver type (mm)	The axis diameter (mm)	Dimensions (mm)			Qty./ Carton	Weight (g)
			D	A	L		
BBD-M50	$\ominus 0.4 \times 3.0$	3	12.5	50	101	1	9
BBD-M75	$\ominus 0.4 \times 3.0$	3	12.5	75	126	1	11
BBD-P00	$\oplus$ No.00	3	12.5	75	126	1	11

- Round shaft screwdriver



WARNING

- Plastic handle is not for insulation. Do not use on live lines.

CAUTION

- It is not a bit-through type screwdriver.



BBD-M50

BBD-M75

BBD-P00



With magnet

WARNING

- Do not misuse screwdrivers for wedge or chisel. Hammering or twisting damages screwdrivers and invite accident at a later date.